

What Screwmax Offer

Written by Administrator

Tuesday, 14 June 2011 13:03 - Last Updated Thursday, 25 July 2013 14:46

We manufacture and supply high quality Hydraulic pumps, Hydraulic motors, Hydraulic cylinders, Hydraulic valves, Steerings, Dump truck parts, Excavator parts, Bulldozer parts, Crusher machinery and parts, etc.

KOMATSU

KOMATSU PUMP: HPV35, HPV55, HPV55T, HPV70, HPV75, HPV90, HPV95, HPV100, HPV105, HPV125, HPV132, HPV160, KMF40, KMF90, KMF125, KMF160, KPV90, KPV160;
MAIN PUMP: PC30-7, PC40-8, PC45R-8, PC50, PC60-3, PC60-5, PC60-6, PC60-7, PC60-8, PC70-6, PC80-3, PC90-1, PC100-3, PC100-5, PC100-6, PC100-7, PC100-8, PC120-3, PC120-5, PC120-6, PC120-7, PC120-8, PC150-3, PC150-5, PC200-1, PC200-2, PC200-3, PC200-5, PC200-6, PC200-7, PC200-8, PC220-3, PC220-5, PC220-6, PC220-7, PC300, PC300-1, PC300-2, PC300-3, PC300-5, PC300-6, PC300-7, PC320, PC350-6, PC360-7, PC400, PC400-1, PC400-2, PC400-3, PC400-5, PC400-6, PC400-7, PC450-6, PC600-7, PC650-3 (P1), PC650-3 (P2), PC650-3 (SP), PC650-5 (P1), PC650-5 (P2), PC650-5 (SP), PC710-5 (P1), PC710-5 (P2), PC710-5 (SP), PC750-6 (P1), PC750-6 (P2), PC800-6 (P1), PC800-6 (P2), PC1000-1 (P1), PC1000-1 (P2), PC1000-1 (SP), PC1100-6 (P1), PC1100-6 (P2), PC1100-6 (P3), PC1600-1 (P1), PC1600-1 (P2), PC1600-1 (SP), WA700-1 (LOADER), WA700-1 (SWITCH), WA800-1 (LOADER), WA800-1 (STEERING), WA800-1 (SWITCH), WA800-2 (LOADER), WA800-2 (STEERING), WA800-2 (SWITCH), WA900-1 (LOADER), WA900-1 (STEERING), WA900-1 (SWITCH), D65EX-12 (HYD), D65PX-12 (HYD), D155AX-3 (HMT), D155AX-3 (HSS);
SWING MOTOR: PC100-1, PC100-2, PC120-1, PC120-2, PC150-1, PC150-3, PC150-5, PC200-1, PC200-2, PC200-3, PC200-5, PC200-6, PC220-1, PC220-2, PC220-3, PC220-5, PC220-6;
TRAVEL MOTOR: PC100-1, PC120-1, PC200-1, PC200-2, PC200-3, PC200-5, PC220-1, PC220-2, PC220-3, PC300-2, PC300-3;

HITACHI

HITACHI PUMP: HPV050, HPV091DS, HPV091ES, HPV091DW, HPV091EW, HPV102FW, HPV102GW, HPV105FW, HPV116C, HPV118, HPVO118, HPV125A, HPV125B, HPV135, HPV145C, HPV145D, HPV145F, HPV145G, HPK055A;
MAIN PUMP: AX30, AX35, EX100, EX100-2, EX100-3, EX100-5, EX100M, EX110, EX120-2, EX120-3, EX120-5, EX200, EX200-2, EX200-3, EX200-5, EX200-6, EX220-2, EX220-3, EX220-5, EX270, EX30, EX30-2, EX300, EX300-1, EX300-2, EX300-3, EX300-5, EX30-2, EX35, EX40, EX400, EX60, EX60-2, EX60-3, EX60-5, EX65, EX70, EX700, EX850, EX90, ZAXIS 100, ZAXIS 110, ZAXIS 200, ZAXIS 210, ZAXIS 230, ZAXIS 270, ZAXIS 300, ZAXIS 310, ZAXIS 330, ZAXIS 350, ZX200-3, ZX330-2, UH063, UH065, UH07-3, UH07-7, UH081,

What Screwmax Offer

Written by Administrator

Tuesday, 14 June 2011 13:03 - Last Updated Thursday, 25 July 2013 14:46

UH083, UH09-7, UH10, UH103, UH12-7, UH121, UH123, UH143, UH16, UH181, UH261;
SWING MOTOR: HTM250, HTM450, HTM500, EX100, EX100-2, EX100-3, EX100M-2, EX120, EX200, EX200-2, EX200-3, EX200-5, EX210, EX220, EX270, EX300, EX60, EX60-2, UH083, ZAXIS 200, ZAXIS 210, ZAXIS 220, ZAXIS 230, ZAXIS 330;
TRAVEL MOTOR: HMGC16, HMGC32, HMGC35, HMGC48, HMGF35, HMGF35, HMGF38A, HMGF49CA, HMGF57AA, HMT045, HMT36A, HMT36FA, HMT107, HMT125AC, HMT134, HMT116, HMT145, EX100, EX120, EX200, EX210, UH07-7, UH083;

CATERPILLAR

CATERPILLAR MAIN PUMP: 12G, 14G, 16G, 120G, 140G, AP12, AP12C, AP14, VRD63, SPK10/10, SPV10/10, SBS80, SBS120, SBS140, PPS140, MCB172, MS180, CAT E110B, CAT E120B, CAT E180B, CAT E200B, CAT 215, CAT 235, CAT 245, CAT 300, CAT E300, CAT E300B, CAT 311, CAT E312, CAT E315, CAT 320, CAT 320B, CAT 320C, CAT E322, CAT E325, CAT 330, CAT 330B, CAT 450, CAT 963, CAT 973, CAT 992, CAT D11R, CAT D6H, CAT D8N, CAT D9R, PSV450, PSV600;
SWING MOTOR: CAT 320B, CAT 330B, CAT E110B, CAT E120B, CAT E200B;
TRAVEL MOTOR: CAT E300B;

KYB

KYB: MSG-27P, MSG-27-18F-5, MSG-44P, MSG-44P-21, MAG-10VP, MAG-33VP-480E-2, MAG-33VP-480E-2, JMV45-28, JMV-53/34, JMV-53-01-VBC, PSVD2-21E, PSVD2-26E, PSVD2-27E, SUMITOMO 280, PSV2-55T, SUMITOMO 265-06, KYB37, KYB87;

LIEBHERR

LIEBHERR MAIN PUMP: LPVD35, LPVD45, LPVD64, LPVD75, LPVD90, LPVD100, LPVD107, LPVD125, LPVD140, LPVD150, LPVD165, LPVD225, LPVD250, LIEBHERR 912;
HYDRAULIC MOTOR: LMF35, LMF45, LMF64, LMF75, LMF90, LMF100, LMF107, LMF125, LMF140, LMF150, LMF165, LMF225, LMF250, FMV075, FMV100, FMV140, FMV160, FMV200, FMV225, 944B;

TADANO

TADANO: TADANO 100, TADANO 150, PAVA8282, PAVA6565;

NACHI

What Screwmax Offer

Written by Administrator

Tuesday, 14 June 2011 13:03 - Last Updated Thursday, 25 July 2013 14:46

NACHI MAIN PUMP: PVD-2B-32L, PVD-2B-34, PVD-2B-34L, PVD-2B-36L, PVD-2B-38, PVD-2B-40, PVD-2B-42, PVD-2B-63, PVD-00B, PVD-0B, PVD-1B, PVD-3B-60L, NACHI 130, PVK-2B-505

Bobcat

BOBCAT: BOBCAT 331, BOBCAT 337

TOSHIBA

TOSHIBA: SG02, SG025, SG04, SG08, SG12, SG15, SG17, SG20, SG25, MFB40, MFB80, MFB150, MFB160, MFB170, MFB180, MFB190, MFB200, MFB250, HD450V-2, DH07, DH08, DH55, LUCUS500

KOBELCO

KOBELCO MAIN PUMP: K903B, K903C, K904D, K905, K907, K907-2, K907C, K907D, K909, K912, K916, SK03, SK03-2, SK035, SK03N2, SK04, SK04-2, SK04N2, SK04W, SK05, SK07, SK07-2, SK07N2, SK09, SK09N2, SK10, SK100, SK100-3, SK100-5, SK12, SK120, SK120-5, SK200-, SK200-3, SK200-5, SK200-6, SK220-3, MA340 (SK220-2), SK300, SK300-2, SK320, SK400-2, SK430, SK60, SK60-3, SK-75, KATO 400, HD450V-2, KATO 1023-3, DNB08, DH55 (HZMD), MS230;

SWING MOTOR: K907D, SK07-2, SK07N2, SK09N2, SK100, SK200, SK200-3, SK200-5, SK300, ;

TRAVEL MOTOR: K907-2, K907D, SK04N2, SK07-2, SK07N2, SK09N2, SK100-3, SK200-3, SK300;

Kawasaki

KAWASAKI: K3SP36C, K3V45DT, K3V63DT, K3V112DT, K3V140DT, K3V180DT, K3V280DT, K3V45BDT, K3V63BDT, K3V112BDT, K3V140BDT, K3V180BDT, K3V280BDT, K5V140, K5V200, NV64, NV84, NV90, NV111, NV137, NV172, NV270, NX15, NVK45, KVC925, KVC930, KVC932;

KAWASAKI MOTOR: M2X63, M2X96 (EX200-2), M2X120, M2X146 (EX200-5), M2X150/170 (EX400), M2X210 (EX270/280/300), M5X130, M5X180, MX150, MX173, MX500, MAG150, MAG170, GM05VL, GM06VL, GM05VA, GM07VA, GM08VA, GM09VA, GM10VA, GM17VA, GM18VA, GM20VA, GM23, GM24VA, GM28VA, GM28VL, GM30H, GM35VA, GM35VL,

GM38VA, GM38VL;

Rexroth

REXROTH: A4VSO40, A4V40, A4VSO45, A4VSO50, A4VSO56, A4VSO71, A4VSO125, A4VSO180, A4VSO250, A4VSO355, A4VSO500, A4VG28, A4VG40, A4VG45, A4VG50, A4VG56, A4V56, A4V71, A4V90, A4V125, A4V250, A4VHW90, A4VG71, A4VTG71, A4VTG90, A4VG125, A4VG180, A4VG250, A10VSO10, A10VSO16, A10VSO18, A10VSO28, A10VSO45, A10VSO56, A10VSO60, A10VO60, A10VO63, A10VSO71, A10VSO85, A10VSO100, A10VSO140, A10VG28, A10VG45, A10VG63, A10VSO63, A10V63, A11VG50, A11VO50, A11VO60, A11VO75, A11VO90, A11VO95, A11VO130, A11VO160, A11VO190, A11VLO190, A11VO250, A11VO260, A2F12, A2F23, A2VK28, A2F28, A2F55, A2F80, A2F107, A2F160, A2F200, A2F225, A2V225, A2F250, A2V500, A2V915, A2F355, A2F500, A2F1000, A2FO10, A2FO12, A2FO16, A2FO23, A2FO28, A2FO32, A2FO45, A2FO56, A2FO63, A2FO80, A2FO107, A2FO125, A2FO160, A2FO180, A2FO200, A2FO250, A2FO355, A2FO500, A2FO1000, A2FM10, A2FM12, A2FM16, A2FM23, A2FM28, A2FM32, A2FM45, A2FM56, A2FM63, A2FM80, A2FM107, A2FM125, A2FM160, A2FM180, A2FM200, A2FM250, A2FM355, A2FM500, A2FM1000, A2FE10, A2FE12, A2FE16, A2FE23, A2FE28, A2FE32, A2FE45, A2FE56, A2FE63, A2FE80, A2FE107, A2FE125, A2FE160, A2FE180, A2FE200, A2FE250, A2FE355, A2FE500, A2FE1000, A7V55, A8V55, A7V80, A8V80, A7V107, A8V107, A7V160, A8V160, A7V200, A8V200, A7V225, A8V225, A7V250, A8V250, A7V355, A8V355, A7V500, A8V500, A7V1000, A8V1000, A6VM12, A6VM28, A6VM55, A6VM80, A6VM107, A6VM160, A6VM200, A6VM250, A6VM355, A6VM500, A6VM1000, A6VE12, A6VE28, A6VE55, A6VE80, A6VE107, A6VE160, A6VE200, A6VE250, A6VE355, A6VE500, A6VE1000, A7VO12, A7VO28, A7VO55, A7VO80, A7VO107, A7VO160, A7VO172, A7VO200, A7VO250, A7VO355, A7VO500, A8VO55, A8VO80, A8VO107, A8VO160, A8VO200, A8VO250;

Linde

LINDE: HPR75, HPR90, HPR100, HPR105, HPR130, HPR160, B2PV35, B2PV50, B2PV75, B2PV105, BPV35, BPV50, BPV70, BPV100, BMV7527, BMV35, BMV55, BMV75, BMV105, BPR140, BPR186, BPR260, HMF50, HPV55T, BMF35, BMF55, BMF75, BMF105, BMF140, HMF63-01, MPR63, HPV130-01;

VOLVO

VOLVO: F11-010, F11-28, F11-39, F11-80, F11-110, F11-150, F11-250, F12-060, F12-080, F12-110-MF-1H;

YUKEN

What Screwmax Offer

Written by Administrator

Tuesday, 14 June 2011 13:03 - Last Updated Thursday, 25 July 2013 14:46

YUKEN: A16, A37, A45, A56, A70, A90, A145, MF16A, A3H100;

VICKERS

VICKERS: PVE19, PVE21, PVH57, PVH74, PVH98, PVH106, PVH131, PVH141, PVB5, PVB6, PVB10, PVB15, PVB20, PVB29, PVB45, PVQ40/50, PVB92, PVB110, SPV14, SPV15, SPV18, PVP76, PV0087, PV092, PV29, PV74, P76, PVG130, PSV450, PSV600, PVT38, PK100, PVXS130, PVXS180, PVXS250, PVSO250, PV250, PMT14/18, PV090, TB35, TB45, LZV30, LZV120, LVWO60, PAVC38, PAVC65, PAVC100, BZ732-100, M12600, HPVMF23(T23C), HPVMF237, T28C, T30C, HD3000, FX260R, MMFO25C, OPV27, 3V-SH2B, MPT044, M44, TA19, TA1919, MFE19, PV080, PV092, PVMO18, PVMO28;

UCHIDA

UCHIDA: AP2D9, AP2D12, AP2D14, AP2D16, AP2D21, AP2D25, AP2D36, AP2D38, AP2D42, A10VD17, A10VD40, A10V43, A10VD71, A8VO55, A8VO80, A8VO107, A8VO160, A8VO250, A8V55, A8V86, A8V115, A8V172;

SAUER DANFOSS

SAUER DANFOSS: PV19, PV20, PV21, PV22, PV23, PV24, PV25, PV26, PV27, MF19, MF20, MF21, MF22, MF23, MF24, MF25, MF26, MF27, PVD45, PVM018, PVM028, MF035, MF500, MPV046, 90R030, 90R042, 90R055, 90R075, 90R100, 90R130, 90R180, 90R250, PV42-28/41, MPT35, MPT44, MFO35, OPV1-23, SPV15, SPV18, SPV6/119;

DAIKIN

DAIKIN SUNDSTRAND: V15, V18, V23, V38, V50, V70, VD2-15A, PV040, PVD21, PVD22, PVD23, PVD24;

EATON

EATON: 3321, 3331, 3322, 4621, 4631, 5421, 5431, 6421, 6423, 7620, 7621, 3932-243, 72400, 78461, 78462, 78463, MKV23, MKV33;

HAWE

What Screwmax Offer

Written by Administrator

Tuesday, 14 June 2011 13:03 - Last Updated Thursday, 25 July 2013 14:46

HAWE: V30D95 (V30Z95), V30D140, V30D250, V60;



PARKER: PVP16, PV180, BMHQ30, PVXS130, PVXS180, PVXS250, PVSO250



SAM HYDRAULIK: HCV70S